



GSTIN : 03ACBPK3400D1ZM  
Excise Regn. No. ACBPK3400DXM001

# G. S. INDUSTRIES

APPROVED BY

**N.S.I.C.**  
**R.D.S.O.**  
**ISO 9001-2008**  
**ISO 14001-2004**

D-146, FOCAL POINT EXTENSION, JALANDHAR-144004

PHONE : (O) 0181-5081474, 0181-2601153

(M) 99882-65025 Fax : 0181-2601153

Website : www.gspaints.com

e-mail : info@gspaints.com

## WARRANTY CERTIFICATE

To,  
Dy.CME/Fur  
MODERN COACH FACTORY,  
RAEBARELI, LALGANJ-229120

Dated 5.12.18

Sub:- Performance warranty certificates.

Ref: - P.O. NO. 06570003.R1760018 DATED 18.08.2017

Name of work: - Supply and Application of Paints for exterior painting and interior Primer painting of LHB DEEN DAYALU coaches on Supply and apply basis.

Dear Sir,

With reference to above, we do here by confirm the warranty for three years of the delivered below mentioned coaches vide your above referred purchase order after application & due inspection at your end.

| S.R. | SHELL NO. | FURNISHING NO. | COACH NO. | Railway NO. | DATE OF COMPLETION |
|------|-----------|----------------|-----------|-------------|--------------------|
| 208. | LWS-86041 | Df-106         | 174095/c  | WR          | 13.11.18           |

The warranty is applicable from date of dispatch against the below mention defects as per RDSO specification no. M&C/PCN/100/2013.

- Gloss level value of applied paint-initial 85 unit(on the date of painting) and after applying anti graffiti coating (recorded final reading by quality department) and minimum 80%, 70% and 60% of recorded final gloss after one year, two years and three years respectively.
- Decolorization of paint film.
- Cracking of paint film.
- Peeling of paint film.
- Blistering of the paint film.

And also as per RDSO specification no. M&C/PCN/127-2009 for anti graffiti coating. If any imperfection is noticed or any defect arise during the warranty period due to improper material used or due to bad workmanship we will be bound to set right the defects/imperfections on free of cost in INDIAN RAILWAYS

Thanking you,