



	Modern Coach Factory Raebareli	DOC NO.: MCF/RBL/QMF 8002
	आधुनिक रेल डिब्बा कारखाना, रायबरेली	REV NO: 01
		DATE: 17.04.2018

## ROLLING STOCK CERTIFICATE

Rolling Stock Certificate No.: MCF/RBL/QC/RSC/2020-21 /1289

RLY	WR	COACH NO	215659/C		DATE OF DISPATCH	19-Mar-21
Type	LWSCN1	Shell No.	20G410	DISPATCH TO	Sr.DME/C&W/MMCT	FUR.NO. LSCN-1838

1. Railway Board's Order No. 2020/M(C)/142/2, DATED- 27.01.2021
2. Tare Weight of Coach : 41.24 Tonnes
3. Carrying Capacity : (a) Seating: 80 (b) Sleeping: 80 (c) Luggage: NIL

## 4. Special feature:

A Choke of 5/6 mm in DV side replace with 9 mm in both type (KBI &amp; Faiv.) letter no. MC/LHB/Brake, DT. 27.09.18

## 5. SHELL LEADING DIMENSIONS:

S NO	DESCRIPTION	DIMENSION (MM)
1	Maximum length over body	23700
2	Maximum width over body	3240
3	Maximum height from Rail Level	4039
4	CBC height/Buffer height from Rail level 1105 +0/-10	NPP / PP 1102/1104

## 6. TRACEABILITY OF SHELL ITEMS:

S NO	ITEM	MAKE/SUPPLIER	SERIAL NO
1	Under frame	PP END M/S-AMIT ENGG	NIL
	Front Part	NPP END M/S-AMIT ENGG	NIL
	Complete	MCF/RBL-AIRCON	20G410
2	Lav. side wall	PP END M/S-RAIL TECH KXH	LAV.1
		NPP END M/S-RAIL TECH KXH	LAV.4
3	Side wall	LH SIDE MCF/RBL-V4U LKO	104
		RH SIDE MCF/RBL-V4U LKO	104
4	End wall	PP END M/S-P.D.STEEL	-----
		NPP END M/S-P.D.STEEL	-----
5	Roof	MCF/RBL	231
6	Centre Buffer Coupler	M/S-SANROCK	PP /NPP 16790/16778

## 7. AIR BRAKE TEST REPORT:

S NO	ITEM	DESCRIPTION	SPEC. VALUE	OBSERVED
1	Full brake application	Reduce pressure of BP from 5.0 to 3.4 kg/cm <sup>2</sup> .	6 – 10 sec.	8 Sec
		Max. pressure in BC	3.0 ±0.15 kg/cm <sup>2</sup> .	3.0 kg/cm <sup>2</sup>
		All Brake are applied	OK	OK
2	Insensitivity	Exhaust BP @ 0.3 kg/cm <sup>2</sup> /min.	No brake application	OK
3	Sensitivity	Exhaust BP @ 0.1 kg/cm <sup>2</sup> /Sec, after 06 Sec.	Brake must apply	OK

## 8. PAINTING DETAILS:

S NO	DESCRIPTION	TYPE OF PAINT	MAKE	APPLICATION BY MCF/ CONTRACTOR (SUPPLY & APPLY)	AVERAGE GLOSS VALUE	DATE OF COMPLETION
1	Paint	P.U	GSI	M/S-GSI	91/90	12-Feb-21
2	Insulation			Satisfactory		

16/06/21  
वरिष्ठ अधिकारी अभियंता  
SSE/QC/MCF/RBL  
गुणवत्ता विभाग  
ने०डि०क्र०, रायबरेली (जालगाँव)







MODERN COACH FACTORY, RAEBARELI

आधुनिक रेल डिब्बा कारखाना, रायबरेली

DOC NO.: MCF/RBL/QMF 8002

REV NO.: 01

DATE: 16.05.2016

## ROLLING STOCK CERTIFICATE

Rolling Stock Certificate No.: MCF/RBL/QC/RSC/2020-21/1289

RLY	W	R	-	Coach No.	2	1	5	6	5	9	/	C	-	DATE OF DISPATCH	1	9	0	3	2	0	2	1
-----	---	---	---	-----------	---	---	---	---	---	---	---	---	---	------------------	---	---	---	---	---	---	---	---

DISPATCH	Sr.DME/C&W/MMCT	Type	L	W	S	C	N	1	Shell No.	2	0	G	4	1	0	FUR.NO	LSCN-1838
----------	-----------------	------	---	---	---	---	---	---	-----------	---	---	---	---	---	---	--------	-----------

## 8. DETAIL OF BOGIES.

ITEMS	NPP Side				PP Side			
Bogie No	202738				202737			
Bogie Type	FIAT				FIAT			
Frame no.	VS- 2097				VS-2111			
Bolster no.	APEX-369				APEX-387			
Axle No	21C - 3653 RWF		21 C - 3976 RWF		20 B - 8467 RWF		21 C - 3432 RWF	
Wheel Dia	917.558	917.518	917.506	917.517	917.55	917.49	917.55	917.534
Wheel Disc No	TZ 09-20 28402-0SE5	TZ 09-20 28400-0SF9	TZ 07-20 33620-0PP9	TZ 09-20 27604-0TD8	TZ 09-20 30952-0TD6	TZ 09-20 30955-0TD6	TZ 09-20 32501-0SF2	TZ 09-20 27681-0SD6
R.B. Nos.	06-20 412471	06-20 411372	06-20 413426	06-20 412181	06-20 411577	07-20 416585	06-20 413499	06-20 414663
CT R B Make	TIMKEN		TIMKEN		TIMKEN		TIMKEN	

## 9. SECONDARY SUSPENSION LOAD DEFLECTION VALUES :-

DESCRIPTION	Bogie NPP side				Bogie PP side			
	Secondary 1		Secondary 2		Secondary 1		Secondary 2	
	Outer	Inner	Outer	Inner	Outer	Inner	Outer	Inner
Make & Nos.	CMAFJ08-20 5101-61	CMGBD02-20 F08- 837-48	CMAFJ08-20 5101-152	CMGBD02-20 F08- 837-65	CMAFJ08-20 5101-141	CMGBD02-20 5101-141	CMAFJ08-20 5101- 139	CMGBD02-20 F08- 837-38
Compressed Ht. at Tested Load	515	471	515	472	516	516	516	469
Alignment deviation (mm)	9	16	10	16	7	7	6	19

## 10. TRACEABILITY OF BOGIE ITEMS :-

S. NO	ITEM	MAKE/ SUPPLIER	SERIAL NO.	
			NPP SIDE	PP SIDE
1.	Yaw Damper	ESCORT	7169,7161	7157,7168
2.	Primary outer Spring	CMAFJ	07-20 1100 (277,354,356,273)	07-20 1100 (351,366,375,316)
3.	Primary Inner Spring	CMAFJ	07-20 1101--(325,73,79,360)	07-20 1101--(358,359,197,340)
4.	Primary Damper	IAI	01-20-(298540,299368,300529,298691)	01-20-(299269,300471,298945,298765)
5.	Secondary Damper	IAI	06-20-(327286,327223)	06-20-(327249,326428)
6.	Lateral Damper	KONI	03-19 01921	03-19 01912
7.	Brake Cylinder	FAV	E20-(040,421,424,308)	E20-(310,391,420,097)
8.	Brake Caliper	FAV	H20-(171,169,174,178)B	H20-(175,173,170,172)B
9.	Brake Disc	AVADH	09-18(48200810,43200841,49201045,50201134)	09-18(50201160,50201150,50201154,50201157)
10.	Ball Joint Control Arm	ARYAN		
11.	Lateral Bump Stop	GMT		
12.	Traction Centre make	RNG		
13.	Traction lever make	JI/TAJ		
14.	Ball joint traction lever	GMT/BASANT		
15.	Ball joint traction centre	PRAG		
16.	Secondary Rubber Pad	TECSPAK		
17.	Rubber Spring	BONY		
18.	Anti roll bar Make	RF		
19.	Roll Link make	RF/BONY		
20.	Fork make	RNG		
21.	Control Arm Upper	KUMAR	N0543,N0837,N9529,D0522	D9080,D4840,D0528,N3818
22.	Control Arm Lower	KUMAR	D0517,N0992,0N9392,N0515	D9832,D9943,D9939,P9853
23.	Phonic Wheel	FAV	FT/KEP-604545	FT/KEP-604545

Signature of SSE/Bogie/QC





Modern Coach Factory Raebareli  
आधुनिक रेल डिब्बा कारखाना, रायबरेली

DOC NO.: MCF/RBL/QMF 8002  
REV NO: 01  
DATE: 17.04.2018

ROLLING STOCK CERTIFICATE  
Rolling Stock Certificate No.: MCF/RBL/QC/RSC/2020-21

RLY	WR	COACH NO	215659/C	DATE OF DISPATCH	19-Mar-21
Type	LWSCN1	Shell No.	20G410	DISPATCH TO	Sr.DME/C&W/MMCT
				FUR.NO.	LSCN-1838

12. TRACEABILITY OF FURNISHING ITEMS:

S NO	ITEM	MAKE/SUPPLIER	SERIAL NO(NPP/PP)
1	Air Brake Module	M/S-FAIVELEY	B21063B
2	Distribution valve	M/S-FAIVELEY	B215569B
3	Pull box	M/S-FAIVELEY	
4	FIBA	NIL	NIL
5	Foot Step	M/s- FABRICON KOLKATA	
6	Decoupling arrangement	M/s-PULSER KOLKATA	
7	Floor board	M/s-SHREE RAM PNL	
8	PVC	M/s-RESPONSIVE INDS DELHI	
9	Lavatory inlay	M/s-SEEMA BHOPAL	
10	UIC Vestibule (PPE)	M/S-ELASTOMER MUMBAI	
11	UIC Vestibule (NPPE)	M/S-ELASTOMER MUMBAI	
12	Gangway bridge mounting (PPE)	M/s- MAHAVEER METAL WORKS, KXH	
13	Gangway bridge mounting (NPPE)	M/s- MAHAVEER METAL WORKS, KXH	
14	Body Side Window	M/S-SHATABDI VADODARA	
15	Emergency Window	M/S-SHATABDI VADODARA	
16	Lavatory/hopper Window	M/s-BEI INDS	
17	Side panel	M/s-HFGW VADODARA	
18	Roof Ceiling	M/s-A.B COMPOSITE	
19	Door way Ceiling	M/s-A.B COMPOSITE	
20	Body Side Doors	M/s-JVR LDH(1,3)+SVARN INFRATEL(2,4)	
21	Vestibule Door(PPE)	M/s-JBM FARIDABAD	
22	Vestibule Door(NPPE)	M/s-JBM FARIDABAD	
23	Bio Tank	M/S-RAIL FAB-02 NOS+JSL LIFE-02 NOS	
24	Presurized Flushing(Elect.pneumatic)	M/S-OASIS	
25	Auxiliary Water Tank	M/S-SHIVALIK FAST MOHALI	
26	Under Slung Water Tank ( 2X685L)	M/S-OASIS	
27	Under Slung Water Tank (1x685 L)	M/S-SHIVALIK FAST MOHALI	
28	Health Faucet	M/S-KAPCO VALVES JUC	
29	Lotah Filler Tap	M/S-KAPCO VALVES JUC	
30	Controlled discharge tap	M/S-AGMECO LTD U.K	
31	Lavatory Doors	M/S-JVR LDH	
32	Seat & Berth	M/S-DURABLE LKO	
33	Ventury grill	NIL	
34	RFID	NIL	

वरिष्ठ अभियंता  
SSE/QC/MCF/RBL  
गुणवत्ता विभाग  
रेडिओका, रायबरेली (लालगंज)

		<b>Modern Coach Factory Raebareilly</b> <b>आधुनिक रेल डिब्बा कारखाना, रायबरेली</b>		DOC NO.: MCF/RBL/QMF 8002 REV NO: 01 DATE: 17.04.2018	
ROLLING STOCK CERTIFICATE Rolling Stock Certificate No.: MCF/RBL/QC/RSC/2020-21					
RLY	WR	COACH NO	215659/C	DATE OF DISPATCH	19-Mar-21
Type	LWSCN1	Shell No.	20G410	DISPATCH TO	Sr.DME/C&W/MMCT
		FUR.NO.	LSCN-1838		
13. MODIFICATION (IF ANY) : NIL 14. DEVIATION (IF ANY) : NIL 15. ITEM FITTED ON THE COACH ON TRIAL : NIL					
S NO	ITEM PARTICULARS	PURPOSE	REPORT Frequency	REFERENCE & PERIOD OF TRIAL	
--	-----	-----	-----	-----	
16. WARRANTY:					
S NO	COMPONENTS	WARRANTY			
1	Brake Pad, wheels, flushing valves, push gravity cocks, moldings, window glasses, mirrors, curtain clutch wire etc. ( items which are consumable in nature)	NIL			
2	Other coach furnishing sub assemblies(bought out items)	24 months from the date of dispatch of coach OR 30months from the date of supply of material whichever is earlier.			
NOTE: 1. This warranty covers free supply of parts which wear out and fails within warranty period of normal service. 2. This doesn't covers faults arising out of accident, non standard maintenance practices, abnormal use or mishandling, vandal activity, arson & deficient/pilferage etc. 3. This doesn't cover any consequential liabilities or damages/loss incurred by anybody; furthermore, it shall in no case extend to repayment, return of the coach or replacement of complete coach. 4. Whether a defective part is to be replaced or repaired shall be at the discretion of MCF/RBL. 5. For any complain/ suggestion please Mail at qualityrcfrbl@gmail.com 6. Painting on supply & apply contract :- supply of material and application shall be warranted for a period of three years from Application for any manufacturing /Application as per clause -4,para- V of RDSO specification no .M&C/PCN/100/2013-Given below					
S.No	Time period	Gloss Retention (initial gloss >85 unit at 60°)	Colour Retention rating on 0-10 scale (initial rating of painted panels/coach or ISC/RAL shade card shall be taken as 10)	Adherence of paints (with each other and with substrate ) Cross-cut tape adhesion test as per ASTM D:3359/97(or latest)	
1	After 1 year	80% of initial gloss	7	5B	
2	After 2 year	70% of initial gloss	6	5B	
3	After 3 year	60% of initial gloss	5	4B	
If any imperfection is noticed or any defect arises during the warranty –period due to improper material used or due to bad workmanship, the contractor shall be bounded to set right the defect/ imperfection on free of cost basis at the base depot of the coach.					
 <b>वरिष्ठ QC/MCF/RBL</b> <b>गुणवत्ता विभाग</b> <b>आधुनिक रेल डिब्बा कारखाना, रायबरेली</b>		 <b>SME/AME/QC/MCF/RBL</b> <b>आधुनिक रेल डिब्बा कारखाना, रायबरेली</b> <b>Modern Coach Factory, Raebareilly</b>		 <b>उप मुख्य गुणवत्ता प्रबन्धक</b> <b>Dy. QC/MCF/RBL</b> <b>आधुनिक रेल डिब्बा कारखाना, रायबरेली</b> <b>Modern Coach Factory, Raebareilly</b>	





GSTIN : 03ACBPK3400D1ZM  
Excise Regn. No. ACBPK3400DXM001

**G. S. INDUSTRIES**

APPROVED BY

**N.S.I.C.  
R.D.S.O.  
ISO 9001-2015  
ISO 14001-2015**

D-146, FOCAL POINT EXTENSION, JALANDHAR-144004

PHONE : (O) 0181-5081474

(M) 99882-65025, 99884-55459

Website : www.gspaints.com

e-mail : info@gspaints.com

## WARRANTY CERTIFICATE

To,  
Dy.CME/FP  
MODERN COACH FACTORY,  
RAEBARELI, LALGANJ-229120

Dated - 19/02/2021

Sub:- Performance warranty certificates.

Ref: - P.O.no 31061800101167 DATED 21.08.2019

Name Of Work: - Pu Paint For Lhb Type Rajdhani Coaches.

Dear Sir,

With reference to above, we do here by confirm the warranty for three years from the date of application of the delivered below mention coaches vide your above referred purchase order after application & due inspection at your end.

SR.	SHELL NO.	FURNISHING NO.	COACH NO.	Railway NO.	DATE OF COMPLETION
250.	LWSCN 20G410	LSCN-1030	915659	✓	12/02/2021


The warranty is applicable from date of dispatch against the below mention defects as per RDSO specification no. M&C/PCN/100/2018.

- Gloss level value of applied paint-initial 85 unit (on the date of painting) and minimum 80%, 70% and 60% of initial gloss after one year, two years and three years respectively from the date of application
- Decolonization of paint film.
- Cracking of paint film.
- Peeling of paint film.
- Blistering of the paint film.

Thanking you,  
For G.S.Industries

Auth.signatory




	<b>Modern Coach Factory Raebareli</b> <b>आधुनिक रेल डिब्बा कारखाना, रायबरेली</b>	DOC NO.: MCF/RBL/QEF/8001
		REV NO: 01
		DATE: 29.06.2020

PAGE 1 OF 4

**FOR ELECTRICAL ITEMS**

**ROLLING STOCK CERTIFICATE OF LHB EOG NON AC SCN COACH.**

ELECTRICAL TEST CERTIFICATE FOR LHB EOG NON AC SCN COACH.						
TYPE COACH		LWSCN		SHELL/COACH NO		215659/C
RAILWAY	WR	ELECT. FIT DATE	17-03-2021	MCF EUR. NO.	LSCN-1838	
Sr. no.	Description of tests					Remarks
1.	PUMP EQUIPMENTS					OK
2.	LIGHTS, NL,LAP CHARGING SOCKETS					OK
3.	WORKING OF ACCIDENTAL,EMERGENCY LIGHTS.					OK
4.	RAILWAY CARRIAGE FAN					OK
5.	WHEEL SLIDE PROTECTION SYSTEM ( WSP )					OK
6.	WORKING OF 9 KVA TRANSFORMER					OK
7.	WORKING OF REGULATED BATTERY CHARGER/EMERGENCY BATTERY CHARGER.					OK
8.	SAFETY :					----
8.1.	FUSES AND THEIR RATING					OK
8.2	CONTROL CIRCUIT					OK
8.3	POWER CIRCUIT					OK

 <b>Senior Section Engineer</b> <b>Quality control / Electrical</b> <b>Modern Coach Factory Raebareli</b>
---





	<b>Modern Coach Factory Raebareli</b> <b>आधुनिकरेलडिब्बाकारखाना, रायबरेली</b>	DOC NO.: MCF/RBL/QEF/8001
		REV NO: 01
		DATE: 29.06.2020

PAGE 2 OF 4

## ROLLING STOCK CERTIFICATE OF LHB/EOG NONAC SCN COACHES

Sr. no.	Description	Drg./Spec no.	Quantity per Coach
01.	Fitment of Switch board cabinet.(set of panel) Make/Sr.no.: <b>HIND</b> On Board: <b>H355.20E.0836</b> HT Panel: <b>H355.20E.0755</b>	EDTS 355, Rev`01`.Am-3	<b>01 SET</b>
02.	Provision of 9 KVA 750/415/190V, 03Ø AC. Make: <b>VIMAL</b> Sr no.: <b>VTC 3089 LHB 4413</b>	RDSO/PE/SPEC/TL 0158, 2010, Rev`0`,Ty I.	<b>01</b>
03.	Mounting of 09KVA TFR.	As per drg no 1.10113.0.76.300.001,Alt -B.	OK
04.	Provision of Pump equipment with pump box. Make: <b>KIND</b> Sr no : <b>KIND/ASY/0050</b> Pump 1: <b>19060299</b> Pump 2: <b>19060300</b>	As per spec no. EDTS186,REV-A,AM-2	<b>01 SET</b>
05.	Provision & Mounting of Pump controller. Make: <b>KIND</b> SL.no.: <b>20050079</b>	As per Spec. EDTS186 Rev-a Am-2, &drg no. CC71328 & LW70020	<b>01</b>
06.	4.5 Kw Under slung type Constant Voltage Regulated Battery charger cum Emergency battery charger Make: <b>SIGNOTRON</b> Sr. no.: <b>09190393</b>	As per spec no. RDSO/PE/SPEC/AC/0183-2015(REV.- 1)	<b>01</b>
07.	Provision of Feeder Junction Box Make : <b>MV ELECTRO SYSTEMS</b>	EDTS-328 REV-C,AM-4,Type- II,COR-2	<b>01 SET</b>
08.	Provision of IVC dummy Socket assembly.	As per Drg. No. LW71302,Alt-nil	<b>01 SET</b>
09.	Battery fuse box +ve Make : <b>INDORAIL</b>	As per LW 71001,Alt- H	<b>01</b>
10.	Battery fuse box -ve Make : <b>AECO</b>	As per LW 71002,Alt-I	<b>01</b>
11.	Provision of Battery boxes/ Cradles. Make: <b>HITECH</b>	As per Drg. No. 110113.0.76.700.005 W/O item 5,22,23,26 & 27,Alt-C or Latest.	<b>01</b>
12.	Provision of batteries Type:110 V, 120 AH VRLA SMF Battery Set. Make: <b>AMARA RAJA</b> Lug Date: <b>06/20</b>	As per RDSO/PE/SPEC/AC/0009-2014 (Rev-2) with inner cell connectors or Latest.	<b>01 SET</b>

**Senior Section Engineer**  
**Quality control / Electrical**  
**Modern Coach Factory Raebareli**







Modern Coach Factory Raebareli  
आधुनिकरेलडिब्बाकारखाना, रायबरेली

DOC NO.: MCF/RBL/QEF/8001

REV NO: 01

DATE: 29.06.2020

PAGE 3 OF 4

ROLLING STOCK CERTIFICATE OF LHB/EOG NONAC SCN COACHES

Sr. no.	Description	Drg./Spec no.	Quantity per Coach
13.	Fitment of Railway carriage Fan 400mm Sweep, 110V AC with crash worthy features. Make: <b>SARIA</b>	As per Drg. No. ICF/SK-7-6-158,alt-g. RDSO/PE/SPEC/TL/0021-2005 (Rev-3) with RCF annex-1,am-1.	<b>30</b>
14.	Fitment of LED Light fittings for Cabin, Doorway and Gangway area. 9 watt. Make : <b>DR AUTO</b>	As per RDSO/PE/SPEC/TL/0091-2016,Rev-1 with RCF Annex-1 .Type-B1.Drg. No. CC76453.	<b>26</b>
15.	Fitment of LED Light fittings for Night Light with berth indication Type-E (1 watt). Make: <b>AGASTYA</b>	As per RDSO/PE/SPEC/TL/0091-2016,Rev-1 with RCF Annex-1, ICF/STB-7-6-053.Type- E. Drg. No. CC76461	<b>10</b>
16.	Fitment of LED Light fittings for Lavatory Lights. 9 Watt. Make: <b>DR AUTO</b>	As per RDSO/PE/SPEC/TL/0091-2016,Rev-1 with RCF Annex-1Type-D. Drg. No. LW76092.	<b>04</b>
17.	Fitment of LED Light fittings for PACIL. Make: <b>AGASTYA</b>	As per RDSO/SPEC/TL/0091-2016,Rev-1 with RCF Annex-1Type-I. Drg. No. LW76098.	<b>02</b>
18.	Fitment of Accidental Emergency Light (AEL) Make: <b>INTEG</b>	As per RDSO/SPEC/AC/0180-2016,Rev-0 ,Type-II.	<b>04</b>
19.	Provision of Cable binder	Drg. No. CC76120,Item - 1,2,3.100mm,200mm,300mm respectively.	<b>OK</b>
20.	Provision of Cable Jacket System.	EDTS-138,Cor-2,Item-5,7,8,9,11.	<b>OK</b>

*Senior Section Engineer*  
Quality control / Electrical  
Modern Coach Factory Raebareli





Modern Coach Factory Raebareli  
आधुनिकरेलडिब्बाकारखाना, रायबरेली

DOC NO.: MCF/RBL/QEF/8001

REV NO: 01

DATE: 29.06.2020

PAGE 4 OF 4

ROLLING STOCK CERTIFICATE OF LHB/EOG NONAC SCN COACHES

Sr. no.	Description	Drg./Spec no.	Quantity per Coach
21.	Provision of Switch plate assembly along with mobile charging sockets. Make: <b>SALZER</b>	EDML-086, Rev-6, Am-1, Table-1, Item-1.	10
22.	Provision of Switch plate assembly along with mobile charging sockets. Make: <b>SALZER</b>	EDML-086, Rev-6, Am-1, Table-1, Item-2.	10
23.	Provision of Switch plate assembly along with mobile charging sockets. Make: <b>SALZER</b>	EDML-086, Rev-5, Am-1, Table-1, Item-3.	20
24.	Provision of High Capacity Inter – Vehicular Coupler Unit (ZS Coupling) (500 A, 750 V, 3ph, 50 Hz). Make:- 1.(NPP): <b>PRIME ELECT.</b> 2.(PP): <b>PRIME ELECT.</b>	As per Spec. no. RDSO/PE/SPEC/AC/0177(Rev.-0)-2013 with annexure-A, B.	01 SET
25.	Mounting of Inter Vehicle coupler	As per drg no.1.10113.0.74.000.001,Alt-B	OK
26.	Provision of Wheel Set Earthing equipment. Make:- NPP: <b>DARSHAN ENTERPRISES</b> PP: <b>DARSHAN ENTERPRISES</b>	EDTS101,REV-C,AM-1	01 SET
27.	Provision of Anti Skid Disk Brake System.(WSP) Make : <b>FAIVELEY</b> Sr no : <b>13039</b>	As per MDTs 077,Rev.-2 M/s"FAIVELEY" or "Knorr Bremse", or "ESCORTS" or "JWL-DAKO-CZ"	01 SET

SSE/EL/QC वरिष्ठ अनुमान अभियन्ता मुम्बई नियंत्रण आ०रे०डि०का० / लालगंज / रायबरेली S.S.E./Elect-QC/M.C.F./LLJ/RBL	AWM(ELECT.)/MCF/RBL SEE(P)/MCF/RBL

आ०रे०डि०का० / लालगंज / रायबरेली  
S.S.E./Elect-QC/M.C.F./LLJ/RBL

स० कार्य प्रबन्धक / विद्युत  
आ०रे०डि०का० / रायबरेली  
A.W.M./Electrical/MCF/RBL