
		Modern Coach Factory Raebareli				DOC NO.: MCF/RBL/QMF 8002	
		आधुनिक रेल डिब्बा कारखाना, रायबरेली				REV NO: 01	
						DATE: 17.04.2018	
ROLLING STOCK CERTIFICATE							
Rolling Stock Certificate No.: MCF/RBL/QC/RSC/2020-21 /1292							
RLY	WR	COACH NO	215662/C			DATE OF DISPATCH	19-Mar-21
Type	LWSCN1	Shell No.	20G220	DISPATCH TO	Sr.DME/C&W/MMCT	FUR.NO.	LSCN-1865
1. Railway Board's Order No. 2020/M(C)/ 142/2, DATED- 27.01.2021 2. Tare Weight of Coach : 41.24 Tonnes 3. Carrying Capacity : (a) Seating: 80 (b) Sleeping: 80 (c) Luggage: NIL 4. Special feature: A Choke of 5/6 mm in DV side replace with 9 mm in both type (KBI & Faiv.) letter no. MC/LHB/Brake, DT. 27.09.18							
5. SHELL LEADING DIMENSIONS:							
S NO	DESCRIPTION					DIMENSION (MM)	
1	Maximum length over body					23700	
2	Maximum width over body					3240	
3	Maximum height from Rail Level					4039	
4	CBC height/Buffer height from Rail level 1105 +0/-10					NPP / PP	1098/1097
6. TRACEABILITY OF SHELL ITEMS:							
S NO	ITEM	MAKE/SUPPLIER	SERIAL NO				
1	Under frame	Front Part	PP END	M/S-ULTRA ENGG	----		
			NPP END	M/S-ULTRA ENGG	----		
		Complete	M/S-ULTRA ENGG	20G220			
2	Lav. side wall	PP END	M/S-DTL PUNE	LAV.1	-----	LAV.2	-----
		NPP END	M/S-DTL PUNE	LAV.4	-----	LAV.3	-----
3	Side wall	LH SIDE	M/S-ECBT	251			
		RH SIDE	M/S-ECBT	251			
4	End wall	PP END	M/S-P.D.STEEL	-----			
		NPP END	M/S-P.D.STEEL	-----			
5	Roof	MCF/RBL	245				
6	Centre Buffer Coupler	M/S-FRONTIETR	PP /NPP	248P1/160P1			
7. AIR BRAKE TEST REPORT:							
S NO	ITEM	DESCRIPTION	SPEC. VALUE	OBSERVED			
1	Full brake application	Reduce pressure of BP from 5.0 to 3.4 kg/cm <sup>2</sup> .	6 – 10 sec.	8 Sec			
		Max. pressure in BC	3.0 ±0.15 kg/cm <sup>2</sup> .	3.0 kg/cm <sup>2</sup>			
		All Brake are applied	OK	OK			
2	Insensitivity	Exhaust BP @ 0.3 kg/cm <sup>2</sup> /min.	No brake application	OK			
3	Sensitivity	Exhaust BP @ 0.1 kg/cm <sup>2</sup> /Sec, after 06 Sec.	Brake must apply	OK			
8. PAINTING DETAILS:							
S NO	DESCRIPTION	TYPE	MAKE	APPLICATION BY MCF/ CONTRACTOR	AVERAGE	DATE OF	
		OF PAINT		(SUPPLY & APPLY)	GLOSS VALUE	COMPLETION	
1	Paint	P.U	GSI	M/S-GSI(WOW)	97/95	16-Mar-21	
2	Insulation	Satisfactory					

  
 वरिष्ठ अभियंता  
 SSE/QC/MCF/RBL  
 गुणवत्ता विभाग  
 रेडिओ, रायबरेली (लालगंज)





MODERN COACH FACTORY, RAEBARELI

आधुनिक रेल डिब्बा कारखाना, रायबरेली

DOC NO.: MCF/RBL/QMF 8002

REV NO.: 01

DATE: 16.05.2016

## ROLLING STOCK CERTIFICATE

Rolling Stock Certificate No.: MCF/RBL/QC/RSC/2020-21/1292

RLY	-	W	R	Coach No.	2	1	5	6	6	2	/	C	-	DATE OF DISPATCH	1	9	0	3	2	0	2	1
-----	---	---	---	-----------	---	---	---	---	---	---	---	---	---	------------------	---	---	---	---	---	---	---	---

DISPATCH	SR.DME/C&W/MMCT	Type	L	W	S	C	N	-	Shell No.	2	0	G	2	2	0	FUR.NO	LSCN-1865
----------	-----------------	------	---	---	---	---	---	---	-----------	---	---	---	---	---	---	--------	-----------

## 8. DETAIL OF BOGIES:

ITEMS	NPP Side				PP Side			
Bogie No	202907				202908			
Bogie Type	FIAT				FIAT			
Frame no.	MCF/RBL/LS-5 - 2884				MCF/RBL/LS-5 - 2999			
Bolster no.	AMIT- 611				AMIT-563			
Axle No	21 C - 3718 RWF		21 C - 3510 RWF		21 C - 4164 RWF		21 C - 4489 RWF	
Wheel Dia	917.396	917.516	917.431	917.493	917.526	917.541	917.515	917.546
Wheel Disc No	TZ 09-20 34606-0TE7	TZ 09-20 29525-0SD4	TZ 09-20 27123-0SF8	TZ 09-20 28358-0SF8	TZ 09-20 22071-0TE6	TZ 09-20 22070-0TE6	TZ 09-20 30453-0TE5	TZ 09-20 29540-0SD4
R.B. Nos.	09-20 426738	09-20 429013	09-20 429162	09-20 427562	09-20 426941	09-20 429149	09-20 426023	09-20 426869
CT R B Make	TIMKEN		TIMKEN		TIMKEN		TIMKEN	

## 9. SECONDARY SUSPENSION LOAD DEFLECTION VALUES :-

DESCRIPTION	Bogie NPP side		Bogie PP side	
	Secondary 1	Secondary 2	Secondary 1	Secondary 2
Make & Nos.	RESISTROFLEX Sr.NO.03-20 14215	RESISTROFLEX Sr.NO.03-20 13959	RESISTROFLEX Sr.NO.06-20 15263	RESISTROFLEX Sr.NO.06-20 15125

## 10. TRACEABILITY OF BOGIE ITEMS :-

S. NO	ITEM	MAKE/ SUPPLIER	SERIAL NO.	
			NPP SIDE	PP SIDE
1.	Yaw Damper	IAI	294835,294903	294724,294569
2.	Primary outer Spring	CMAFI	06-20-1100-(279,277,274,280)	06-20-1100-(253,254,249,255)
3.	Primary Inner Spring	CMAFI	06-20-1101 (62,60,1,25)	06-20-1101-(362,324,329,270)
4.	Primary Damper	IAI	01-20-(300671,300026,300189,300205)	01-20-(300280,298971,299878,300939)
5.	Secondary Damper	GABRIEL	07-20-(2198,2201)	07-20-(2194,2195)
6.	Lateral Damper	KONI	04-19 02144	04-19 01756
7.	Brake Cylinder	ESCORT	62817,692294,62295,62816	62829,62286,62287,62830
8.	Brake Caliper	ESCORT	39395,39040,39041,39394	39390,39032,39033,39391
9.	Brake Disc	KBI	24243859 0002-51/20,24243859 0003-51/20 24241018 0019-49/20,24241017 0075-49/20	24243854 0002-50/20,24241024 0071-50/20 24247101 0023-02/21,24247101 0024-02/21
10.	Ball Joint Control Arm	GMT		
11.	Lateral Bump Stop	GMT		
12.	Traction Centre make	RNG		
13.	Traction lever make	TAJ		
14.	Ball joint traction lever	BONY		
15.	Ball joint traction centre	ARYAN		
16.	Leveling Valve	FAV	L19-(451,854)	H20-(446,439)
17.	Check Valve	FAV	K19- 332	F20-187
18.	Anti roll bar Make	SF		
19.	Roll Link make	RF+BONY SAI/BONY		
20.	Fork make	RNG		
21.	Control Arm Upper	SF	104,1,33,278	23,178,58,26
22.	Control Arm Lower	SF	11,22,66,41	277,15,265,88
23.	Phonic Wheel	ESCORT	-	-

Signature of SSE/Bogie/QC





Modern Coach Factory Raebareli  
आधुनिक रेल डिब्बा कारखाना, रायबरेली

DOC NO.: MCF/RBL/QMF 8002  
REV NO: 01  
DATE: 17.04.2018

ROLLING STOCK CERTIFICATE  
Rolling Stock Certificate No.: MCF/RBL/QC/RSC/2020-21

RLY	WR	COACH NO	215662/C	DATE OF DISPATCH	19-Mar-21
Type	LWSCN1	Shell No.	20G220	DISPATCH TO	Sr.DME/C&W/MMCT
				FUR.NO.	LSCN-1865

12. TRACEABILITY OF FURNISHING ITEMS:

S NO	ITEM	MAKE/SUPPLIER	SERIAL NO(NPP/PP)
1	Air Brake Module	M/S-ESCORTS	2021020829
2	Distribution valve	M/S-ESCORTS	2102A829
3	Pull box	M/S-KBI	
4	FIBA	M/S-KBI	11501/29,11562/29
5	Foot Step	M/s- FABRICON KOLKATA	
6	Decoupling arrangement	M/s-PULSER KOLKATA	
7	Floor board	M/s-SHREE RAM PNL	
8	PVC	M/s-RESPONSIVE INDS DELHI	
9	Lavatory inlay	M/s-SEEMA BHOPAL	
10	UIC Vestibule (PPE)	M/S-SUNCREST KOLKATA	
11	UIC Vestibule (NPPE)	M/S-SUNCREST KOLKATA	
12	Gangway bridge mounting (PPE)	M/s- MAHAVEER METAL WORKS, KXH	
13	Gangway bridge mounting (NPPE)	M/s- MAHAVEER METAL WORKS, KXH	
14	Body Side Window	M/S-SHATABDI VADODARA	
15	Emergency Window	M/S-SHATABDI VADODARA	
16	Lavatory/hopper Window	M/s-BEI INDS	
17	Side panel	M/s-HFGW VADODARA	
18	Roof Ceiling	M/s-A.B COMPOSITE	
19	Door way Ceiling	M/s-A.B COMPOSITE	
20	Body Side Doors	M/s-JVR LDH	
21	Vestibule Door(PPE)	M/s-JBM FARIDABAD	
22	Vestibule Door(NPPE)	M/s-JBM FARIDABAD	
23	Bio Tank	M/S-RAIL FAB-02 NOS+JSL LIFE-02 NOS	
24	Presurized Flushing(Elect.pneumatic)	M/S-AIR FLOW	
25	Auxiliary Water Tank	M/S-SHIVALIK FAST MOHALI	
26	Under Slung Water Tank ( 2X685L)	M/S-OASIS	
27	Under Slung Water Tank (1x685 L)	M/S-AMIT ENGG. MOHALI	
28	Health Faucet	M/S-KAPCO VALVES JUC	
29	Lotah Filler Tap	M/S-KAPCO VALVES JUC	
30	Controlled discharge tap	M/S-AGMECO LTD U.K	
31	Lavatory Doors	M/S-JVR LDH	
32	Seat & Berth	M/S-DURABLE LKO	
33	Ventury grill	NIL	
34	RFID	NIL	

16/06/20  
वर्गिकृत अभियंता  
SSE/QC/MCF/RBL

गुणवत्ता विभाग  
रेडि0का0, रायबरेली (लालगंज)



**Modern Coach Factory Raebareli**  
**आधुनिक रेल डिब्बा कारखाना, रायबरेली**

DOC NO.: MCF/RBL/QMF 8002  
REV NO: 01  
DATE: 17.04.2018

**ROLLING STOCK CERTIFICATE**  
Rolling Stock Certificate No.: MCF/RBL/QC/RSC/2020-21

RLY	WR	COACH NO	215662/C	DATE OF DISPATCH	19-Mar-21
Type	LWSCN1	Shell No.	20G220	DISPATCH TO	Sr.DME/C&W/MMCT
				FUR.NO.	LSCN-1865

13. MODIFICATION (IF ANY) : NIL

14. DEVIATION (IF ANY) : NIL

15. ITEM FITTED ON THE COACH ON TRIAL : NIL

S NO	ITEM PARTICULARS	PURPOSE	REPORT Frequency	REFERENCE & PERIOD OF TRIAL
--	-----	-----	-----	-----

**16. WARRANTY:**




S NO	COMPONENTS	WARRANTY
1	Brake Pad, wheels, flushing valves, push gravity cocks, moldings, window glasses, mirrors, curtain clutch wire etc. ( items which are consumable in nature)	NIL
2	Other coach furnishing sub assemblies(bought out items)	24 months from the date of dispatch of coach OR 30months from the date of supply of material whichever is earlier.

**NOTE:**

- This warranty covers free supply of parts which wear out and fails within warranty period of normal service.
- This doesn't covers faults arising out of accident, non standard maintenance practices, abnormal use or mishandling, vandal activity, arson & deficient/pilferage etc.
- This doesn't cover any consequential liabilities or damages/loss incurred by anybody; furthermore, it shall in no case extend to repayment, return of the coach or replacement of complete coach.
- Whether a defective part is to be replaced or repaired shall be at the discretion of MCF/RBL.
- For any complain/ suggestion please Mail at qualityrcfrbl@gmail.com
- Painting on supply & apply contract :- supply of material and application shall be warranted for a period of three years from Application for any manufacturing /Application as per clause -4,para- V of RDSO specification no .M&C/PCN/100/2013-Given below

S.No	Time period	Gloss Retention (initial gloss >85 unit at 60°)	Colour Retention rating on 0-10 scale (initial rating of painted panels/coach or ISC/RAL shade card shall be taken as 10)	Adherence of paints (with each other and with substrate ) Cross-cut tape adhesion test as per ASTM D:3359/97(or latest)
1	After 1 year	80% of initial gloss	7	5B
2	After 2 year	70% of initial gloss	6	5B
3	After 3 year	60% of initial gloss	5	4B

If any imperfection is noticed or any defect arises during the warranty-period due to improper material used or due to bad workmanship, the contractor shall be bounded to set right the defect/ imperfection on free of cost basis at the base depot of the coach.

 16/06/21 व.सि.सिंह SSE/QC/MCF/RBL	 17/06 SME/AME/QC/MCF/RBL	 17/06/2021 उप मुख्य गुणवत्ता प्रबन्धक Dy. Chief Quality Manager Modern Coach Factory, Raebareli
--	--	---

रेडिंक, रायबरेली (लालगंज)

आधुनिक रेल डिब्बा कारखाना, रायबरेली  
Modern Coach Factory, Raebareli

Modern Coach Factory, Raebareli





GSTIN : 03ACBPK3400D1ZM  
Excise Regn. No. ACBPK3400DXM001

# G. S. INDUSTRIES

APPROVED BY

**N.S.I.C.**

**R.D.S.O.**

**ISO 9001-2015**

**ISO 14001-2015**

D-146, FOCAL POINT EXTENSION, JALANDHAR-144004

PHONE : (O) 0181-5081474

(M) 99882-65025, 99884-55459

Website : www.gspaints.com

e-mail : info@gspaints.com

## WARRANTY CERTIFICATE

Date- 18/3/2021

To,  
DY.CME/FUR/PROGRESS  
MODERN COACH FACTORY,  
RAEBARELI, LALGANJ-229120

Sub:- PERFORMANCE WARRANTY CERTIFICATE

PO NO. 31061800101632 DATED 01.10.2019

NAME OF WORK: - SUPPLY AND APPLY OF PU BASED WET ON WET APPLICABLE EXTERIOR PAINTING SYSTEM FOR LHB COACHES. AS PER SCOPE OF WORK AND MMDTS-18034 REV-02 WITH AMENDMENT NO. MP/RBL/B8 DT 28/05/2019 (EPOXY ELASTIFIED PAINT INSIDE THE COACH NOT TO BE CARRIED OUT, PAINTING CYCLE TIME WILL BE 30 HRS AS MENTION IN MMDTS-18034 REV-02)

DEAR SIR,

With reference to above, we do here by confirm the warranty for six years of the date of application of delivered below mentioned coaches vide your above referred purchase order after application & due inspection at your end.

SR.	SHELL NO.	FURNISHING NO.	COACH NO.	Railway NO.	DATE OF COMPLETION
1. 286	LWSCN 206220	LSCN-1865	215662	WR	26/02/2021 16/03/2021

The warranty is applicable from date of dispatch against the below mention defects as per MCF specification no. MMDTS 18034 REV-2


- Gloss level value of applied paint-initial 95 unit(on the date of painting) and minimum 90%,85%,75% & 70% of initial gloss after 6 months, one years, four years and six years respectively from the date of application.
- Decolonization of paint film.
- Cracking of paint film.
- Peeling of paint film.
- Blistering of the paint film.
- The coach is warranted 6years for gloss retention, premature failure in colour retention

Vor 1.3

Asst.






	<b>Modern Coach Factory Raebareli</b> <b>आधुनिकरेलडिब्बाकारखाना, रायबरेली</b>	DOC NO.: MCF/RBL/QEF/8001
		REV NO: 01
		DATE: 29.06.2020

PAGE 1 OF 4

FOR ELECTRICAL ITEMS

ROLLING STOCK CERTIFICATE OF LHB EOG NON AC SCN COACH.

ELECTRICAL TEST CERTIFICATE FOR LHB EOG NON AC SCN COACH.						
TYPE COACH		LWSCN		SHELL/COACH NO		215662/C
RAILWAY		WR	ELECT. FIT DATE	18-03-2021	MCF EUR. NO.	LSCN-1865
Sr. no.	Description of tests					Remarks
1.	PUMP EQUIPMENTS					OK
2.	LIGHTS, NL,LAP CHARGING SOCKETS					OK
3.	WORKING OF ACCIDENTAL,EMERGENCY LIGHTS.					OK
4.	RAILWAY CARRIAGE FAN					OK
5.	WHEEL SLIDE PROTECTION SYSTEM ( WSP )					OK
6.	WORKING OF 9 KVA TRANSFORMER					OK
7.	WORKING OF REGULATED BATTERY CHARGER/EMERGENCY BATTERY CHARGER.					OK
8.	SAFETY :					----
8.1.	FUSES AND THEIR RATING					OK
8.2.	CONTROL CIRCUIT					OK
8.3.	POWER CIRCUIT					OK

 <b>Senior Section Engineer</b> <b>Quality control / Electrical</b> <b>Modern Coach Factory Raebareli</b>
---





	<b>Modern Coach Factory Raebareli</b> <b>आधुनिकरेलडिब्बाकारखाना, रायबरेली</b>	DOC NO.: MCF/RBL/QEF/8001
		REV NO: 01
		DATE: 29.06.2020

PAGE 2 OF 4

## ROLLING STOCK CERTIFICATE OF LHB/EOG NONAC SCN COACHES

Sr. no.	Description	Drg./Spec no.	Quantity per Coach
01.	Fitment of Switch board cabinet.(set of panel) Make/Sr.no.: <b>HIND</b> On Board: <b>H355.20E.0788</b> HT Panel: <b>H355.20E.0722</b>	EDTS 355, Rev`01'.Am-3	<b>01 SET</b>
02.	Provision of 9 KVA 750/415/190V, 03Ø AC. Make: <b>VIMAL</b> Sr no.: <b>VTC 3089 LHB 4347</b>	RDSO/PE/SPEC/TL 0158, 2010, Rev`0',Ty I.	<b>01</b>
03.	Mounting of 09KVA TFR.	As per drg no 1.10113.0.76.300.001,Alt -B.	<b>OK</b>
04.	Provision of Pump equipment with pump box. Make: <b>KIND</b> Sr no : <b>KIND/ASY/0063</b> Pump 1: <b>19060325</b> Pump 2: <b>19060326</b>	As per spec no. EDTS186,REV-A,AM-2	<b>01 SET</b>
05.	Provision & Mounting of Pump controller. Make: <b>HIND</b> SL.no.: <b>20/03/058</b>	As per Spec. EDTS186 Rev-a Am-2, & drg no. CC71328 & LW70020	<b>01</b>
06.	4.5 Kw Under slung type Constant Voltage Regulated Battery charger cum Emergency battery charger Make: <b>SIGNOTRON</b> Sr. no.: <b>08201784</b>	As per spec no. RDSO/PE/SPEC/AC/0183-2015(REV.- 1)	<b>01</b>
07.	Provision of Feeder Junction Box Make : <b>AECO</b>	EDTS-328 REV-C,AM-4,Type- II,COR-2	<b>01 SET</b>
08.	Provision of IVC dummy Socket assembly.	As per Drg. No. LW71302,Alt-nil	<b>01 SET</b>
09.	Battery fuse box +ve Make : <b>INDORAIL</b>	As per LW 71001,Alt- H	<b>01</b>
10.	Battery fuse box -ve Make : <b>AECO</b>	As per LW 71002,Alt-I	<b>01</b>
11.	Provision of Battery boxes/ Cradles. Make: <b>PRADEEP TRANSCORE</b>	As per Drg. No. 110113.0.76.700.005 W/O item 5,22,23,26 & 27,Alt-C or Latest.	<b>01</b>
12.	Provision of batteries Type:110 V, 120 AH VRLA SMF Battery Set. Make: <b>AMARA RAJA</b> Lug Date: <b>06/20</b>	As per RDSO/PE/SPEC/AC/0009-2014 (Rev-2) with inner cell connectors or Latest.	<b>01 SET</b>

**Senior Section Engineer**  
**Quality control / Electrical**  
**Modern Coach Factory Raebareli**





Modern Coach Factory Raebareli  
आधुनिकरेलडिब्बाकारखाना, रायबरेली

DOC NO.: MCF/RBL/QEF/8001

REV NO: 01

DATE: 29.06.2020

PAGE 3 OF 4


ROLLING STOCK CERTIFICATE OF LHB/EOG NONAC SCN COACHES

Sr. no.	Description	Drg./Spec no.	Quantity per Coach
13.	Fitment of Railway carriage Fan 400mm Sweep, 110V AC with crash worthy features. Make: <b>KAPSONS</b>	As per Drg. No. ICF/SK-7-6-158,alt-g. RDSO/PE/SPEC/TL/0021-2005 (Rev-3) with RCF annex-1,am-1.	<b>30</b>
14.	Fitment of LED Light fittings for Cabin, Doorway and Gangway area. 9 watt. Make : <b>DR AUTO/RT VISION</b>	As per RDSO/PE/SPEC/TL/0091-2016,Rev-1 with RCF Annex-1 .Type-B1.Drg. No. CC76453.	<b>26</b>
15.	Fitment of LED Light fittings for Night Light with berth indication Type-E (1 watt). Make: <b>DHINGRA</b>	As per RDSO/PE/SPEC/TL/0091-2016,Rev-1 with RCF Annex-1, ICF/STB-7-6-053.Type- E. Drg. No. CC76461	<b>10</b>
16.	Fitment of LED Light fittings for Lavatory Lights. 9 Watt. Make: <b>DR AUTO</b>	As per RDSO/PE/SPEC/TL/0091-2016,Rev-1 with RCF Annex-1 Type-D. Drg. No. LW76092.	<b>04</b>
17.	Fitment of LED Light fittings for PACIL. Make: <b>AGASTYA</b>	As per RDSO/SPEC/TL/0091-2016,Rev-1 with RCF Annex-1 Type-I. Drg. No. LW76098.	<b>02</b>
18.	Fitment of Accidental Emergency Light (AEL) Make: <b>INTEG</b>	As per RDSO/SPEC/AC/0180-2016,Rev-0 ,Type-II.	<b>04</b>
19.	Provision of Cable binder	Drg. No. CC76120,Item - 1,2,3.100mm,200mm,300mm respectively.	<b>OK</b>
20.	Provision of Cable Jacket System.	EDTS-138,Cor-2,Item-5,7,8,9,11.	<b>OK</b>

*Senior Section Engineer*  
Quality control / Electrical  
Modern Coach Factory Raebareli







	<b>Modern Coach Factory Raebareli</b> <b>आधुनिकरेलडिब्बाकारखाना, रायबरेली</b>	DOC NO.: MCF/RBL/QEF/8001
		REV NO: 01
		DATE: 29.06.2020

PAGE 4 OF 4

## ROLLING STOCK CERTIFICATE OF LHB/EOG NONAC SCN COACHES

Sr. no.	Description	Drg./Spec no.	Quantity per Coach
21.	Provision of Switch plate assembly along with mobile charging sockets. Make: <b>SALZER</b>	EDML-086, Rev-6, Am-1, Table-1, Item-1.	<b>10</b>
22.	Provision of Switch plate assembly along with mobile charging sockets. Make: <b>SALZER</b>	EDML-086, Rev-6, Am-1, Table-1, Item-2.	<b>10</b>
23.	Provision of Switch plate assembly along with mobile charging sockets. Make: <b>SALZER</b>	EDML-086, Rev-5, Am-1, Table-1, Item-3.	<b>20</b>
24.	Provision of High Capacity Inter – Vehicular Coupler Unit (ZS Coupling) (500 A, 750 V, 3ph, 50 Hz). Make:- 1.(NPP): <b>PRIME ELECT.</b> 2.(PP): <b>PRIME ELECT.</b>	As per Spec. no. RDSO/PE/SPEC/AC/0177(Rev.-0)-2013 with annexure-A, B.	<b>01 SET</b>
25.	Mounting of Inter Vehicle coupler	As per drg no.1.10113.0.74.000.001,Alt-B	<b>OK</b>
26.	Provision of Wheel Set Earthing equipment. Make:- NPP: <b>DARSHAN ENTERPRISES</b> PP: <b>DARSHAN ENTERPRISES</b>	EDTS101,REV-C,AM-1	<b>01 SET</b>
27.	Provision of Anti Skid Disk Brake System.(WSP) Make : <b>ESCORTS</b> Sr no : <b>200600-62308-0089</b>	As per MDTs 077,Rev.-2 M/s"FAIVELEY" or "Knorr Bremse", or "ESCORTS" or "JWL-DAKO-CZ"	<b>01 SET</b>

	
<b>वरिष्ठ अनुसंधान विज्ञान</b> <b>गुणवत्ता नियंत्रण</b> <b>आ०रे०डि०का० / लालगंज / रायबरेली</b> <b>S.S.E./Elect-QC/M.C.F./RBL</b>	<b>AWM(ELECT.)/MCF/RBL</b> <b>SEE(P)/MCF/RBL</b> <b>स० कार्य प्रबन्धक / विद्युत</b> <b>आ०रे०डि०का० / रायबरेली</b> <b>A.W.M./Electrical/MCF/RBL</b>

